

# Firmware for ioLogik E1200 Series (ioLogik E1214/E1214-T) Release Notes

Version: v3.3

Build: Build 22072210

Release Date: Aug 03, 2022

## **Applicable Products**

ioLogik E1214, ioLogik E1214-T

## **Supported Operating Systems**

N/A

## **New Features**

- Adds the default password "moxa".
- Adds a Password and Login Policy.
- Adds the Notification Message function.

## Enhancements

• Adds the DHCP Option 12 "Server Name".

## **Bugs Fixed**

• Ethernet/IP cannot establish second input only session.

#### Changes

N/A

## Notes



Version: v3.2

#### Build: Build20111915

Release Date: Dec 25, 2020

## **Applicable Products**

ioLogik E1214-T, ioLogik E1214

## **Supported Operating Systems**

N/A

#### **New Features**

• Safe Mode supports Ethernet/IP protocol.

**Enhancements** 

N/A

## **Bugs Fixed**

- DHCP mode will not get the Gateway IP.
- The counter value is reset after power failure when booting up.
- The serial number is displayed incorrectly on the web console.
- Ethernet/IP implicit messages are sent to port 2222 by default.

#### Changes

N/A

## Notes



Version: v3.1

#### Build: Build19110615

Release Date: Nov 26, 2019

## Applicable Products

ioLogik E1214, ioLogik E1214-T

#### **Supported Operating Systems**

N/A

#### **New Features**

- EtherNet/IP registration on Moxa's licensing website is no longer required.
- Added case insensitive content-length for RESTful API.

## **Enhancements**

N/A

## **Bugs Fixed**

- Fixed inaccurate counter value when using Modbus to start a pulse (E1210/E1212/E1213).
- Fixed opposite on/off pulse width display on web console (E1211/E1212/E1214).
- Fixed that the offset scaling value will reset after changing the Alias name (E1260).
- Fixed self-rebooting when entering URL in the browser for the configuration file.
- Fixed EDS file import connection error.

• Fixed failure when using save counter on power failure and reset counter at the same time (E1210/E1212/E1213).

- Fixed inaccurate counter value when using high frequency (E1210/E1212/E1213).
- Fixed that the trap community name is not included in the export file.
- Fixed that EtherNet/IP cannot use the "Set Attribute Single" service.
- Added an enable RESTful API setting in the configuration file.

#### Changes

N/A

## Notes



Version: v3.0

#### Build: Build17111512

Release Date: Jan 16, 2018

## **Applicable Products**

ioLogik E1214-T, ioLogik E1214

## **Supported Operating Systems**

N/A

#### **New Features**

- Added OPTIONS method for RESTful API.
- Added quick access URI for RESTful API.

## Enhancements

- Added SNMP Trap Community Setting on web console.
- Mentioned max. 16 characters on password setting page.

#### **Bugs Fixed**

- Fixed DHCP lease time did not ask for extension when half of the lease time elapsed.
- Closed IP forwarding function (Port 0).
- Closed UDP Port 161 when SNMP agent is disabled.
- Fixed invalid token issue on login page when using Firefox.
- Fixed RESTful API header case-sensitive issue.
- Fixed invalid token issue on DO setting page.

#### Changes

N/A

#### Notes

- This version of firmware works with the ioSearch V2.0 or later only.
- Update only the next or the previous released firmware version to prevent from system failure.



Version: v2.5

#### Build: Build16091211

**Release Date: N/A** 

## **Applicable Products**

ioLogik E1214, ioLogik E1214-T

## Supported Operating Systems

N/A

#### **New Features**

- Added EtherNet/IP protocol.
- Added RESTful API.
- Added new registers for Modbus/TCP protocol.
- Added new OIDs of SNMP protocol.
- Modbus, EtherNet/IP, RESTful Services can be disabled (default: enable).
- Added sending heartbeat to 9500 port of MX-AOPC UA Server after heartbeat function is enabled.
- Increased password length from 8 to 16.
- Added checking special character function for preventing from Cross-Site Scripting.
- Changed sending password from GET to POST method.

#### Enhancements

N/A

#### **Bugs Fixed**

- Fixed file transfer with Chrome browser issue (e.g. firmware update, configuration import or export).
- Fixed wrong display ON/OFF width value of pulse mode on channel setting page.

#### Changes

N/A

#### Notes



Version: v2.4	Build: Build16053018
Release Date: N/A	
Applicable Products	
ioLogik E1214, ioLogik E1214-T	
Supported Operating Systems	
N/A	
New Features	
Improve protocol efficiency with ioLogik 2500	) series .
Enhancements	
N/A	
Bugs Fixed	
N/A	
Changes	
N/A	
Notes	
N/A	



Version: v2.3

#### Build: Build15031013

**Release Date: N/A** 

## **Applicable Products**

ioLogik E1214, ioLogik E1214-T

## **Supported Operating Systems**

N/A

#### **New Features**

- Support ioLogik 2500 expansion mode.
- Support safe mode auto-clear function.
- Support counter initial value function.
- Support DO Power ON Delay function.

#### **Enhancements**

N/A

## **Bugs Fixed**

- Unable to disable the P2P Heart beat interval.
- When the Heart beat Interval Time = 0, the P2P server will reconnect continuously.
- When the P2P client heartbeat is set to a value larger than 256, the time interval will be incorrect.

• When one DI channel mapping to multiple DO channels in P2P mode, the update interval will be fixed.

#### Changes

N/A

## Notes



Version: v2.0

#### Build: Build13041515

Release Date: N/A

## **Applicable Products**

ioLogik E1214, ioLogik E1214-T

## Supported Operating Systems

N/A

## **New Features**

- Support SNMP protocol.
- Add P2P heartbeat function .

## **Enhancements**

N/A

## **Bugs Fixed**

• When power failing, counter storage fail.

#### Changes

N/A

## Notes

- This version of firmware works with the ioSearch V1.5 or later only.
- Use web console when upgrading firmware from V1.0 to V1.10.



Release Date: N/A   Applicable Products   oLogik E1214, ioLogik E1214-T   Supported Operating Systems   V/A   New Features   V/A   Enhancements   • Wording change for DO pulse output .   Sugs Fixed   V/A   Changes   V/A   Notes	2010416
oLogik E1214, ioLogik E1214-T Supported Operating Systems V/A New Features V/A Enhancements • Wording change for DO pulse output . Bugs Fixed V/A Changes V/A	
Supported Operating Systems V/A New Features V/A Enhancements • Wording change for DO pulse output . Sugs Fixed V/A Changes V/A	
V/A New Features V/A Enhancements Wording change for DO pulse output . Bugs Fixed V/A Changes	
New Features N/A Enhancements Wording change for DO pulse output . Bugs Fixed N/A Changes	
V/A Enhancements • Wording change for DO pulse output . Bugs Fixed V/A Changes	
Enhancements Wording change for DO pulse output . Bugs Fixed V/A Changes	
Wording change for DO pulse output . Bugs Fixed V/A Changes	
Bugs Fixed N/A Changes N/A	
N/A Changes N/A	
<b>Changes</b> N/A	
V/A	
Notes	
I/A	



Version: v1.9	Build: Build11112413
Release Date: N/A	
Applicable Products	
ioLogik E1214, ioLogik E1214-T	
Supported Operating Systems	
N/A	
New Features	
N/A	
Enhancements	
<ul> <li>Ensured system to work properly after</li> </ul>	r unstable power condition.
Bugs Fixed	
N/A	
Changes	
N/A	
Notes	
N/A	



Version: v1.8

#### Build: Build11092917

**Release Date: N/A** 

## **Applicable Products**

ioLogik E1214, ioLogik E1214-T

#### **Supported Operating Systems**

N/A

#### **New Features**

- Added Locating I/O function in General Settings.
- Added Modbus address function code=0x08 for "ECHO" function.
- Added Modbus address for Peer-to-peer connection and safe mode status.
- Peer-to-peer connection and safe mode status are displayed on Channels Safe Mode.

#### **Enhancements**

- Improved firmware upgrading speed.
- Removed Modbus/TCP ID checking mechanism.

#### **Bugs Fixed**

• One DO/AO channel should only be peered by one DI/AI channel.

• No matter safe mode is triggered by Watchdog or Peer-to-peer, the DO/AO status under safe mode should be the same.

#### Changes

N/A

#### Notes